



Photograph No. 191: Looking north-east, demolition in ODC, Panorama of site: Photo 7 of 33  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 192: Looking NE, loading truck at ODC, Panorama of site: Photo 8 of 33  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 193: Looking east, loading truck at ODC, Panorama of site: Photo 9 of 33  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 194: Looking further east from trailer area, Panorama of site: Photo 10 of 33  
Date: May 20, 2010. Photo taken by: TH





Photograph No. 195: Looking north from west side of HMS building, Panorama of site:  
Photo 11 of 33  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 196: Looking at HMS building, Panorama of site: Photo 12 of 33  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 197: Looking at loading dock from south of HMS building, Panorama of site:  
Photo 13 of 33  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 198: View of boats on the west side of HMS building, Panorama of site:  
Photo 14 of 33  
Date: May 20, 2010. Photo taken by: TH





Photograph No. 199: View of boats on the west side of HMS building, Panorama of site:  
Photo 15 of 33  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 200: View of demolition in ODC, Panorama of site: Photo 16 of 33  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 201: View west road near air monitoring station, Panorama of site:  
Photo 17 of 33  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 202: Looking north from west road of ODC, Panorama of site: Photo 18 of 33  
Date: May 20, 2010. Photo taken by: TH





Photograph No. 203: Looking NE from west road of ODC, Panorama of site: Photo 19 of 33  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 204: Looking east from west road of ODC, Panorama of site: Photo 20 of 33  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 205: Looking SE from west road of ODC, Panorama of site: Photo 21 of 33  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 206: Looking SE from west road of ODC, Panorama of site: Photo 22 of 33  
Date: May 20, 2010. Photo taken by: TH





Photograph No. 207: Looking SE from west road of ODC, Panorama of site: Photo 23 of 33  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 208: Looking south from west road of ODC, Panorama of site: Photo 24 of 33  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 209: Looking west side of building from cont. cell , Panorama of site:  
Photo 25 of 33  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 210: Looking west side of building from cont. cell , Panorama of site:  
Photo 26 of 33  
Date: May 20, 2010. Photo taken by: TH





Photograph No. 211: Looking south of building from cont. cell, Panorama of site:  
Photo 27 of 33  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 212: Looking east from cont. cell, Panorama of site: Photo 28 of 33  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 213: Looking further east from cont. cell, Panorama of site: Photo 29 of 33  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 214: Looking further SE from cont. cell, Panorama of site: Photo 30 of 33  
Date: May 20, 2010. Photo taken by: TH





Photograph No. 215: Looking further SE from cont. cell, Panorama of site: Photo 31 of 33  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 216: Looking further SE from cont. cell, Panorama of site: Photo 32 of 33  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 217: Looking further east from cont. cell, Panorama of site: Photo 33 of 33  
Date: May 20, 2010. Photo taken by: TH



Photograph No. 218: View of demolition in ODC area (looking west)  
Date: May 20, 2010. Photo taken by: MD





Photograph No. 219: Brick pile located near demolished area  
Date: May 20, 2010. Photo taken by: CN



Photograph No. 220: Window removal from the wall located in TR area  
Date: May 20, 2010. Photo taken by: CN



Photograph No. 221: Windows removed from the south wall of P4  
Date: May 20, 2010. Photo taken by: CN



Photograph No. 222: Excavator with shear cutting waste material  
Date: May 20, 2010. Photo taken by: CN





Photograph No. 223: Dozer collecting material in north area of ODC  
Date: May 20, 2010. Photo taken by: CN



Photograph No. 224: Demolition in ODC (looking south)  
Date: May 20, 2010. Photo taken by: CN



Photograph No. 225: View of ODC from north of HMS building (looking north)  
Date: May 20, 2010. Photo taken by: CN



Photograph No. 226: View of the north wall of the building (looking south east)  
Date: May 20, 2010. Photo taken by: CN





Photograph No. 227: Looking at HMS Storage Building, Panorama of site: Photo 1 of 13  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 228: Looking at waste metal pile, Panorama of site: Photo 2 of 13  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 229: ODC demolition, Panorama of site: Photo 3 of 13  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 230: Active demolition, Panorama of site: Photo 4 of 13  
Date: May 24, 2010. Photo taken by: TH





Photograph No. 231: ODC Active demolition, Panorama of site: Photo 5 of 13  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 232: Demolished area –Stockpiled material, Panorama of site: Photo 6 of 13  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 233: Demolished area, Panorama of site: Photo 7 of 13  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 234: Demolished area, Panorama of site: Photo 8 of 13  
Date: May 24, 2010. Photo taken by: TH





Photograph No. 235: East part of office area, Panorama of site: Photo 9 of 13  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 236: East part of office area (continued), Panorama of site: Photo 10 of 13  
Date: May 24, 2010. Photo taken by: TH



Photograph No.237: East part of office area (continued), Panorama of site: Photo 11 of 13  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 238: East part of office area (continued), Panorama of site: Photo 12 of 13  
Date: May 24, 2010. Photo taken by: TH





Photograph No. 239: East part of office area (continued), Panorama of site: Photo 13 of 13  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 240: Looking at Boiler to the west of ODC, Panorama of site: Photo 1 of 4  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 241: Looking at Boiler to the west of ODC, Panorama of site: Photo 2 of 4  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 242: Looking at ODC demolition, Panorama of site: Photo 3 of 4  
Date: May 24, 2010. Photo taken by: TH





Photograph No. 243: Demolished area in ODC (looking east), Panorama of site: Photo 4 of 4  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 244: Looking at south of boiler room from west of ODC  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 245: Looking east at boiler room from road west of ODC, Panorama of site:  
Photo 1 of 7  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 246: Looking east from west road of ODC (continued), Panorama of site:  
Photo 2 of 7  
Date: May 24, 2010. Photo taken by: TH





Photograph No. 247: Looking east from west road of ODC (continued), Panorama of site:  
Photo 3 of 7

Date: May 24, 2010. Photo taken by: TH



Photograph No. 248: Looking east from west road of ODC (continued), Panorama of site:  
Photo 4 of 7

Date: May 24, 2010. Photo taken by: TH



Photograph No. 249: Looking north from west road of ODC (continued), Panorama of site:  
Photo 5 of 7  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 250: Looking north from west road of ODC (continued), Panorama of site:  
Photo 6 of 7  
Date: May 24, 2010. Photo taken by: TH





Photograph No. 251: Looking north from west road of ODC (continued), Panorama of site:  
Photo 7 of 7  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 252: North side of ODC, Panorama of site: Photo 1 of 10  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 253: Looking east from north side of ODC (continued), Panorama of site:  
Photo 2 of 10  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 254: Looking east from north side of ODC, Panorama of site: Photo 3 of 10  
Date: May 24, 2010. Photo taken by: TH





Photograph No. 255: Looking east from north side of ODC, Panorama of site: Photo 4 of 10  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 256: Looking east from north side of ODC, Panorama of site: Photo 5 of 10  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 257: Looking east from north side of ODC, Panorama of site: Photo 6 of 10  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 258: Looking east from north side of ODC, Panorama of site: Photo 7 of 10  
Date: May 24, 2010. Photo taken by: TH





Photograph No. 259: Looking east from north side of ODC, Panorama of site: Photo 8 of 10  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 260: Looking east from north side of ODC, Panorama of site: Photo 9 of 10  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 261 : Looking east from north side of ODC, Panorama of site: Photo 10 of 10  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 262: ODC area from top of west containment area, Panorama of site:  
Photo 1 of 8  
Date: May 24, 2010. Photo taken by: TH





Photograph No. 263: Looking east from top of containment area, Panorama of site:  
Photo 2 of 8

Date: May 24, 2010. Photo taken by: TH



Photograph No. 264: Looking east from top of containment area, Panorama of site:  
Photo 3 of 8

Date: May 24, 2010. Photo taken by: TH



Photograph No. 265: Looking east from top of containment area, Panorama of site: Photo 4 of 8  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 266 : Looking east from top of containment area, Panorama of site:  
Photo 5 of 8  
Date: May 24, 2010. Photo taken by: TH





Photograph No. 267: Looking east from top of containment area, Panorama of site: Photo 6 of 8  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 268: Looking east from top of containment area, Panorama of site: Photo 7 of 8  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 269: Looking east from top of containment area, Panorama of site: Photo 8 of 8  
Date: May 24, 2010. Photo taken by: TH



Photograph No. 270: Typical water dust suppression  
Date: May 24, 2010. Photo taken by: TH





Photograph No. 271: Progress of demolition, looking west from area near trailers,  
Panorama of site: Photo 1 of 9  
Date: June 1, 2010. Photo taken by: TH



Photograph No. 272: Progress of demolition, looking west from area near trailer,  
Panorama of site: Photo 2 of 9  
Date: June 1, 2010. Photo taken by: TH



Photograph No. 273: Progress of demolition, looking north west from area near trailer,  
Panorama of site: Photo 3 of 9  
Date: June 1, 2010. Photo taken by: TH



Photograph No. 274: Progress of demolition, looking north west from area near trailer,  
Panorama of site: Photo 4 of 9  
Date: June 1, 2010. Photo taken by: TH





Photograph No. 275: Progress of demolition, looking north from area near trailer, Panorama of site: Photo 5 of 9  
Date: June 1, 2010. Photo taken by: TH



Photograph No. 276: Progress of demolition, looking north from area near trailer, Panorama of site: Photo 6 of 9  
Date: June 1, 2010. Photo taken by: TH



Photograph No. 277: Progress of demolition, looking north east from area near trailer,  
Panorama of site: Photo 7 of 9  
Date: June 1, 2010. Photo taken by: TH



Photograph No. 278: Progress of demolition, looking north east from area near trailer,  
Panorama of site: Photo 8 of 9  
Date: June 1, 2010. Photo taken by: TH





Photograph No. 279: Progress of demolition, looking east from area near trailer,  
Panorama of site: Photo 9 of 9  
Date: June 1, 2010. Photo taken by: TH



Photograph No. 280: Progress of demolition, sorting and loading, looking from northwest  
corner of ODC, Panorama of site: Photo 1 of 7  
Date: June 1, 2010. Photo taken by: TH



Photograph No. 281: Progress of demolition, sorting and loading, looking from northwest corner of ODC, Panorama of site: Photo 2 of 7  
Date: June 1, 2010. Photo taken by: TH



Photograph No. 282: Progress of demolition, sorting and loading, looking from northwest corner of ODC, Panorama of site: Photo 3 of 7  
Date: June 1, 2010. Photo taken by: TH





Photograph No. 283: Progress of demolition, sorting and loading, looking from northwest corner of ODC, Panorama of site: Photo 4 of 7  
Date: June 1, 2010. Photo taken by: TH



Photograph No. 284: Progress of demolition, sorting and loading, looking from northwest corner of ODC, Panorama of site: Photo 5 of 7  
Date: June 1, 2010. Photo taken by: TH



Photograph No. 285: Progress of demolition, sorting and loading, looking from northwest corner of ODC, Panorama of site: Photo 6 of 7  
Date: June 1, 2010. Photo taken by: TH



Photograph No. 286: Progress of demolition, sorting and loading, looking from northwest corner of ODC, Panorama of site: Photo 7 of 7  
Date: June 1, 2010. Photo taken by: TH



Photograph No. 287: Demolition activities, view from the north area, Panorama of site:  
Photo 1 of 8  
Date: June 1, 2010. Photo taken by: TH



Photograph No. 288: Demolition activities, view from the north area, Panorama of site:  
Photo 2 of 8  
Date: June 1, 2010. Photo taken by: TH





Photograph No. 289: Demolition activities, view from the north area, Panorama of site:  
Photo 3 of 8  
Date: June 1, 2010. Photo taken by: TH



Photograph No. 290: Demolition activities, view from the north area, Panorama of site:  
Photo 4 of 8  
Date: June 1, 2010. Photo taken by: TH



Photograph No. 291: Demolition activities, view from the north area, Panorama of site:  
Photo 5 of 8  
Date: June 1, 2010. Photo taken by: TH



Photograph No. 292: Demolition activities, view from the north area, Panorama of site:  
Photo 6 of 8  
Date: June 1, 2010. Photo taken by: TH




Photograph No. 293: Demolition activities, view from the north area, Panorama of site:  
Photo 7 of 8  
Date: June 1, 2010. Photo taken by: TH



Photograph No. 294: Demolition activities, view from the north area, Panorama of site:  
Photo 8 of 8  
Date: June 1, 2010. Photo taken by: TH





Photograph No. 295: Demolition of roof, looking at interior of P-2  
Date: June 1, 2010. Photo taken by: TH



Photograph No. 296: Demolition near P-2  
Date: June 1, 2010. Photo taken by: TH



Photograph No. 297: Looking east at demolition activities from slab area in ODC  
Date: June 1, 2010. Photo taken by: TH



Photograph No. 298: View of Dock area  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 299: View of wall to the east of dock area  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 300: View of south wall from dock area through east end of building  
Date: June 7, 2010. Photo taken by: CN





Photograph No. 301: View of south wall of P3 and P4  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 302: South wall near office area  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 303: Storage trailer and south wall near office area  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 304: Waste pile west of office area  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 305: Office areas  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 306: Concrete slab in NDC area  
Date: June 7, 2010. Photo taken by: CN





Photograph No. 307: Approach to the concrete slab of ODC area  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 308: HMS building and approach to the concrete slab  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 309: Scrap metal pile near HMS building  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 310: Scrap metal pile near HMS building  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 311: HMS building  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 312: Boat near HMS building  
Date: June 7, 2010. Photo taken by: CN





Photograph No. 313: Boats near HMS building  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 314: View of ODC from HMS building  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 315: View of ODC from HMS building  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 316: View of concrete floor with waste piles in ODC  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 317: Waste piles in ODC  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 318: Dozer collecting waste  
Date: June 7, 2010. Photo taken by: CN





Photograph No. 319: General waste pile  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 320: View of NDC, TR , DS and P1  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 321: View of NDC, TR, DS and P1  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 322: View of P2  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 323: View of Dock area in P2  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 324: View of Dock area in P2  
Date: June 7, 2010. Photo taken by: CN





Photograph No. 325: View of Dock area in P2  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 326: View of Guard Shack  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 327: East side of the building  
Date: June 7, 2010. Photo taken by: CN



Photograph No. 328: View of demolition near P4, looking east, Panorama of site: Photo 1 of 10  
Date: June 11, 2010. Photo taken by: TH



Photograph No. 329: View of demolition near P4, looking east, Panorama of site: Photo 2 of 10  
Date: June 11, 2010. Photo taken by: TH



Photograph No. 330: View of slab in P4, looking north east, Panorama of site: Photo 3 of 10  
Date: June 11, 2010. Photo taken by: TH





Photograph No. 331: View of slab, looking north, Panorama of site: Photo 4 of 10  
Date: June 11, 2010. Photo taken by: TH



Photograph No. 332: View of slab, looking north, Panorama of site: Photo 5 of 10  
Date: June 11, 2010. Photo taken by: TH



Photograph No. 333: View of slab, looking north west, Panorama of site: Photo 6 of 10  
Date: June 11, 2010. Photo taken by: TH



Photograph No. 334: View of slab, looking north west, Panorama of site: Photo 7 of 10  
Date: June 11, 2010. Photo taken by: TH



Photograph No. 335: View of slab, looking west, Panorama of site: Photo 8 of 10  
Date: June 11, 2010. Photo taken by: TH



Photograph No. 336: View of slab, looking west, Panorama of site: Photo 9 of 10  
Date: June 11, 2010. Photo taken by: TH





Photograph No. 337: View of demolition near P4, Panorama of site: Photo 10 of 10  
Date: June 11, 2010. Photo taken by: TH



Photograph No. 338: Worker putting plastic cover on the shutter of building located to the east  
Date: June 14, 2010. Photo taken by: MD



Photograph No. 339: Demolition work in P 4  
Date: June 16, 2010. Photo taken by: MD



Photograph No. 340: Wall in P3 standing to reduce wind in work area  
Date: June 16, 2010. Photo taken by: MD





Photograph No. 341: Demolition in office area  
Date: June 21, 2010. Photo taken by: MD



Photograph No. 342: Demolition in office area  
Date: June 21, 2010. Photo taken by: MD





Photograph No. 343: Dock area east of office area during demolition  
Date: June 21, 2010. Photo taken by: MD



Photograph No. 344: View of P3 and P4 during office demolition  
Date: June 21, 2010. Photo taken by: MD



Photograph No. 345: Demolition of wall in dock area  
Date: June 22, 2010. Photo taken by: MD



Photograph No. 346: Demolition in dock area  
Date: June 22, 2010. Photo taken by: MD



Photograph No. 347: Demolition in dock area  
Date: June 22, 2010. Photo taken by: MD



Photograph No. 348: Water truck spraying water in dock area  
Date: June 22, 2010. Photo taken by: MD





Photograph No. 349: Demolition in dock area  
Date: June 22, 2010. Photo taken by: MD



Photograph No. 350: Demolition in dock area  
Date: June 23, 2010. Photo taken by: MD



Photograph No. 351: Demolition in dock area  
Date: June 23, 2010. Photo taken by: CN



Photograph No. 352: Waste piles in P2  
Date: June 23, 2010. Photo taken by: CN





Photograph No. 353: View of concrete slab, looking west, Panorama of site: Photo 1 of 7  
Date: June 24, 2010. Photo taken by: TH



Photograph No. 354: View of concrete slab, looking south, Panorama of site: Photo 2 of 7  
Date: June 24, 2010. Photo taken by: TH





Photograph No. 355: View of concrete slab, looking south, Panorama of site: Photo 3 of 7  
Date: June 24, 2010. Photo taken by: TH



Photograph No.356: View of concrete slab, looking south east, Panorama of site: Photo 4 of 7  
Date: June 24, 2010. Photo taken by: TH



Photograph No. 357: View of concrete slab, looking south east, Panorama of site: Photo 5 of 7  
Date: June 24, 2010. Photo taken by: TH



Photograph No. 358: View of concrete slab, looking south east, Panorama of site: Photo 6 of 7  
Date: June 24, 2010. Photo taken by: TH





Photograph No. 359: View of concrete slab, looking east, Panorama of site: Photo 7 of 7  
Date: June 24, 2010. Photo taken by: TH



Photograph No. 360: Tent around the boiler for asbestos abatement on the north side  
Date: June 30, 2010. Photo taken by: MD





Photograph No. 361: Decontamination station and water truck near the containment  
Date: July 1, 2010. Photo taken by: MD